Visor screws - Mounting instructions
Vis de visière - Instructions de montage


HKar13

CHARLY
BEST OF AIR

VITESSE
Tom Gratzner

Place the enclosed washers - with the smooth side facing the visor - between the helmet and the visor as shown below. Tighten the screws until the desired level of movement of the visor is achieved. The use of a screwdriver is usually not required for this purpose.

Warning: Over-tightening the screws can damage the inserts on the helmet and make them unusable!



Placez les rondelles fournies - avec le côté lisse tourné vers la visière - entre le casque et la visière comme indiqué ci-dessous.
Serrez les vis jusqu'à ce que la fluidité de la visière soit atteinte. L'utilisation d'un tournevis n'est généralement pas nécessaire pour cette partie.

Avertissement: Un serrage excessif des vis peut endommager les inserts du casque et les rendre inutilisables!