AIR TURQUOISE SA | PARA-TEST.COM
Route du Pré-au-Comte 8 ▲ CH-1844 Villeneuve ▲ +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses
and paraglider reserve parachutes

paragliding by air turquoise

Harness Structural test Report - LTF

Inspection certificate number: **PH_300.2020**

Manufacturer data:

Manufacturer name:	**Supair SAS**
Representative:	**Laurent Chiabaut**
Street:	**Parc Altais / 34, rue Adrastée**
Post code place:	**74650 Chavanod**
Country:	**France**

Sample data:

Name:	**Walibi 3**
Type:	**ABS**
Size:	**M**
Serial number:	**WI3-V9.1**
Impact pad type: (1)	**Foam**
Clip-in weight [kg]:	**120**
Date of test:	**22.05.2020**

Atmosphere AGL:

[C°]	**23.2**
RH [%]	**48**
[hPa]	**979.2**

Summary of Structural test

Test id	-	Ref.	Setup	Req. Load [g]	Req. Load [N]	Min. duration [s]	Result
02	V	5.3.2.1	Default flying position	6	7200	10	**POSITIVE**
03	V	5.3.2.2	Default flying position	15	18000	5	**POSITIVE**
04	V	5.3.2.3	Asymmetric, one riser	6	7200	10	**POSITIVE**
07	V	5.3.2.6	Asymmetric, negative	4.5	5400	10	**POSITIVE**
09		5.3.2.4	Rescue attachments	15	18000	5	**n/a**
13	V	5.3.2.7	Flying position before landing	15	18000	5	**POSITIVE**
14		5.3.2.5	Towing	5	6000	10	**n/a**

Rescue deployment test

Test id	-	LTF NfL II 91/09	Setup	Min load [N]	Max. load [N]	Measured [N]	Result
RRDT	V	6.1.5	Default flying position	20	70	**67.41**	**POSITIVE**

Rescue Deployment Handle strength test

Test id	-	EN 12491	Setup	Req. Load [N]	Min. duration [s]	Breaking strength [N]	Result
RRST	V	5.3.2	Two end points of handle	700	10	**2965.07**	**POSITIVE**

Manufacture	Instrument	Type no	S/N	Validity Calibration
HBM	Load Sensor GE01	1-S9M/50KN-1	31314643	04.09.2023
Burster	Sensor Burster	8431-10000	1185483	04.09.2023
JDC elec	Geos n°11 Skywatch	Geos n°11	Unit11	18.06.2025

Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with
Airworthiness Requirements **LTF NfL II 91/09** - **EN12491:2015** 5.3.2

The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20

(1) If Impact pad available, see test report no. 94.22 and inspection certificate no. 94.20


Calculated value in tests reports include the value minus the uncertainty (on safe side) / The uncertainty stated is the expanded uncertainty obtained by multiplying the standard uncertainty by the coverage factor k = 2. The value of the measurand lies within the assigned range of values with a probability of 95%.


This declaration must not be reproduced in part without the written permission of AIR TURQUOISE SA.

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Harness Structural test **Test ID 02**

Standard	**LTF NfL II 91/09**
Reference	**5.3.2.1**
Test setup	**Default flying position**
Attachment points	**Both main riser attachment (3,4)**
Anchor points	**Dummy (B1, B2)**
Required load [g]	**6**
Required load [N]	**7200**
Minimum test duration [s]	**10**
Result	
Test duration [s]	**12.5**
Any signs of structural failure	**No**
Test results	**POSITIVE**







The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Harness Structural test **Test ID 03**

Standard	**LTF NfL II 91/09**
Reference	**5.3.2.2**
Test setup	**Default flying position**
Attachment points	**Both main riser attachment (3,4)**
Anchor points	**Dummy (B1, B2)**
Required load [g]	**15**
Required load [N]	**18000**
Minimum test duration [s]	**5**
Result	
Test duration [s]	**8.6**
Any signs of structural failure	**No**
Test results	**POSITIVE**







The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Harness Structural test **Test ID 04**

Standard	**LTF NfL II 91/09**
Reference	**5.3.2.3**
Test setup	**Asymmetric, one riser**
Attachment points	**One main riser attachment (3)**
Anchor points	**Dummy (B1,B2)**
Required load [g]	**6**
Required load [N]	**7200**
Minimum test duration [s]	**10**
Result	
Test duration [s]	**16.9**
Any signs of structural failure	**No**
Test results	**POSITIVE**





The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20

AIR TURQUOISE SA | PARA-TEST.COM
Route du Pré-au-Comte 8 ▲ CH-1844 Villeneuve ▲ +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses
and paraglider reserve parachutes

paragliding by air turquoise


Inspection certificate number: **PH_300.2020** model: **Walibi 3**


Harness Structural test **Test ID 07**

Standard	**LTF NfL II 91/09**
Reference	**5.3.2.6**
Test setup	**Asymmetric, negative**
Attachment points	**One main riser attachment (3 or 4) downwards**
Anchor points	**Dummy (9)**
Required load [g]	**4.5**
Required load [N]	**5400**
Minimum test duration [s]	**10**

Result

Test duration [s]	**13.5**
Any signs of structural failure	**No**
Test results	**POSITIVE**







The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Harness Structural test **Test ID 13**

Standard	**LTF NfL II 91/09**
Reference	**5.3.2.7**
Test setup	**Flying position before landing**
Attachment points	**Both main riser attachment (3,4)**
Anchor points	**Dummy (7,8)**
Required load [g]	**15**
Required load [N]	**18000**
Minimum test duration [s]	**5**
Result	
Test duration [s]	**8.1**
Any signs of structural failure	**No**
Test results	**POSITIVE**





The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20


AIR TURQUOISE SA | PARA-TEST.COM
Route du Pré-au-Comte 8 ▲ CH-1844 Villeneuve ▲ +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses
and paraglider reserve parachutes

paragliding by air turquoise

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Rescue Deployment Test		**Test ID RRDT**
Standard	**LTF NfL II 91/09**	
Reference	**6.1.5**	
Test setup	**Default flying position**	
Attachment points	**Sensor connect to handle, and pull in opening direction**	
	The test is to simulate the load required to open the emergency parachute(1st action).	
Min. Required load [N]	**20**	
Max. Required load [N]	**70**	
Result		
Load for first action [N]	**67.41**	
Test results	**POSITIVE**	



The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20


AIR TURQUOISE SA | PARA-TEST.COM
Route du Pré-au-Comte 8 ▲ CH-1844 Villeneuve ▲ +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses
and paraglider reserve parachutes

paragliding by air turquoise

Inspection certificate number: **PH_300.2020** model: **Walibi 3**

Rescue Deployment Handle strength test		**Test ID RRST**
Standard	**EN12491:2015**	
Reference in standard	**5.3.2**	
Test setup	**Two end points of handle**	
Attachment points	**Sensor connect to end of handle, pull on the other side**	
	The handle must support min 700 N for 10 s, after measure breaking strength	
Min. Required load [N]	**700**	
Minimum test duration [s]	**10**	
Result		
Test duration [s]:	**18.5**	
Breaking strength [N]	**2965.07**	
Test results	**POSITIVE**	



The validation of this test report is given by the signature of the test manager on the Inspection Certificate no 94.20